

ATTACHMENT 1C.2

**Introduction - Cat I and II Soil Removal, Backfill/
Cover Placement, Borrow Source Delineation and
Groundwater Hydraulic Barrier
East Property Assessment Area**



Introduction - Cat I and II Soil Removal, Backfill/Cover Placement, Borrow Source Delineation and Groundwater Hydraulic Barrier

East Property Assessment Area

Introduction:

As described in Response Action Plan (RAP) Worksheet 1.0 (page 7), response actions for soil of the East Property Assessment Area (East Property AA) principally involve excavation of affected soil and on-site disposal as either Category I material or Category II material. Category I material was excavated from the East Property AA at Area 4 and the Category I Material Storage Area. The Category I material was excavated and disposed of in the Cell 4 landfill. Category II materials were excavated and placed in the Category II Material Storage Area on the East Property AA.

Also within the East Property AA, the East Borrow Source (EBS) area is used for the excavation of clean native soil to be used as backfill and cover material elsewhere on the property. A groundwater control system, the Groundwater Hydraulic Barrier (GHB) is also located on the East Property in the North Arroyo.

Activities at the East Property AA were described in the following sections of the RAP:

- RAP Worksheet 1.0 (pages 7 and 20)
- RAP Worksheet 2.0 (pages 2 and 6)

Supporting Documentation in This Attachment

The following subsections are provided in this attachment:

- 1C.2.1 Category I and II removals
- 1C.2.2 Cat II Material Storage Area
- 1C.2.3 East Borrow Source
- 1C.2.4 Groundwater Hydraulic Barrier