


CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project: (Project #)
 Path: Z:\GIS\Projects\EN\ASARCO_EIPaso\GIS\MXD\RAP\Revised\Fig 1 Plant Entrance Contaminated Soil Excavation_rv1.mxd Date: 12/15/2016 Time: 10:40:22 AM



LEGEND:			
	ALLOQUOTS FOR 5 POINT COMPOSITE SOIL SAMPLE LABELED ENTRANCE ON TABLE 1		COMPACTED NATIVE SOIL WITH VEGETATION
	PROPERTY BOUNDARY		CATEGORY II SOIL COVER
	AREA BOUNDARY		EXCAVATIONS
	ASPHALT AREAS FROM FORMER SITE OPERATIONS		LINED STORMWATER RETENTION POND
	LOW PERMEABILITY COVER		AFFECTED OFF-SITE PROPERTY (SEE NOTE 1)
	LINED ARMOR STONE		PAVED AREAS COMPLETED TO CATEGORY II REMEDIATION STANDARDS
	SLOPE STABILIZATION AND DRAINAGE IMPROVEMENTS, ON-SITE		AFFECTED OFF-SITE PROPERTY (SEE NOTE 1)

Note:
 1. Details of response action will be coordinated with off-site property owner.



FORMER EL PASO SMELTER SITE EL PASO, TEXAS	
PLANT ENTRANCE RESPONSE ACTION	
	FIGURE 1