




CITY: Highlands Ranch DIV/GROUP: GIS DB: BG  
 Project (Project #):  
 Path: G:\GIS\ASARCO\_EIPaso\GIS\MXD\RII\_Updated\Response To Comments\Fig 4-22 Cadmium\_SoilLocations\_PBA2.mxd Date: 4/25/2014 Time: 10:59:49 AM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
  - DETECTED > SCREENING LEVEL
  - HISTORICAL ARROYO TRACE LINES
  - AREA BOUNDARY
  - FINES PILE BOUNDARY
  - BONEYARD BOUNDARY
  - PROPERTY BOUNDARY

**NOTE:**  
 Screening Level (RRR SAI-Ind = 1500 mg/kg)  
**Bolded Value** exceeds screening level  
*Italics* indicate below the water table  
 J = Estimated Value  
 U = Not detected at or above reporting limit  
 Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE  
EL PASO, TEXAS

**CADMIUM DISTRIBUTION IN SOIL  
PARKER BROTHERS ARROYO/BONEYARD**

**MALCOLM  
PIRNIE**

**FIGURE  
4-22**