


CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #): PBA1.mxd Date: 9/13/2013 Time: 3:22:24 PM
 Path: I:\ASARCO - El Paso\GIS\MXD\RI_ Revised\Fig 4-25 Lead_Soil_locations



LEGEND:



- DETECTED ≤ SCREENING LEVEL
- DETECTED > SCREENING LEVEL
- HISTORICAL ARROYO TRACE LINES
- PROPERTY BOUNDARY
- AREA BOUNDARY
- FINES PILE BOUNDARY
- BONEYARD BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 1000 mg/kg)

Bolded Value exceeds screening level
Italics indicate below the water table

J = Estimated Value
 U = Not detected at or above reporting limit

Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
EL PASO, TEXAS

**LEAD DISTRIBUTION IN SOIL
PARKER BROTHERS ARROYO/FINES PILE**

**MALCOLM
PIRNIE**

**FIGURE
4-25**