


CITY: Highlands Ranch DIV/GROUP: GIS DB: BG  
 Project (Project #):  
 Path: I:\ASARCO - El Paso\GIS\MDIRI\_ Revised\Fig 4-38 Mercury\_SoilLocations\_Pond1.mxd Date: 9/13/2013 Time: 3:28:45 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
  - DETECTED > SCREENING LEVEL
  - HISTORICAL ARROYO TRACE LINES
  - PROPERTY BOUNDARY
  - AREA BOUNDARY

**NOTE:**  
 Screening Level (RRR SAI-Ind = 0.15 mg/kg)



**Bolded** Value exceeds screening level

*Italics* indicate below the water table

J = Estimated Value

U = Not detected at or above reporting limit

Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE  
EL PASO, TEXAS

**MERCURY DISTRIBUTION IN SOIL  
POND 1 ARROYO**

**MALCOLM  
PIRNIE**

**FIGURE  
4-38**