


CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #):
 Path: I:\ASARCO - El Paso\GIS\MXD\RI_ Revised\Fig 4-34 Mercury_Soil Locations_SouthTerrace.mxd Date: 9/13/2013 Time: 3:27:30 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - PROPERTY BOUNDARY
 - AREA BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 0.15 mg/kg)

Bolded Value exceeds screening level


Italics indicate below the water table

J = Estimated Value

U = Not detected at or above reporting limit


Date of Aerial Photo: 2009

Sample ID	Depth (ft bgs)	Mercury Concentration in mg/kg
BH8-10	40 (10-11)	40
	13 (15-16)	13



FORMER EL PASO SMELTER SITE
EL PASO, TEXAS

**MERCURY DISTRIBUTION IN SOIL
SOUTH TERRACE ARROYO**



**FIGURE
4-34**