



CITY: Highlands Ranch DIV/GROUP: GIS DB: BG  
 Project (Project #):  
 Path: I:\ASARCO - El Paso\GIS\MDIR\ Revised\Fig 4-39 Antimony\_Soil Locations Pond56.mxd Date: 9/13/2013 Time: 3:32:15 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
  - DETECTED > SCREENING LEVEL
  - HISTORICAL ARROYO TRACE LINES
  - PROPERTY BOUNDARY
  - AREA BOUNDARY

**NOTE:**  
 Screening Level (RRR SAI-Ind = 490 mg/kg)  
**Bolded** Value exceeds screening level  
*Italics* indicate below the water table  
 J = Estimated Value  
 U = Not detected at or above reporting limit  
 Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE EL PASO, TEXAS	
<b>ANTIMONY DISTRIBUTION IN SOIL POND 5,6 ARROYO</b>	
	<b>FIGURE 4-39</b>