



CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #):
 Path: I:\ASARCO - El Paso\GIS\MXDR\ Revised\Fig 4-44 Antimony_SoilLocations_AcidPlant.mxd Date: 9/13/2013 Time: 3:34:36 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY
 - AREA BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 490 mg/kg)
Bolded Value exceeds screening level
Italics indicate below the water table
 J = Estimated Value
 U = Not detected at or above reporting limit
 Date of Aerial Photo: 2009

Sample ID
ZCP-SB02
9.33 (0-0.5)
13.1 (4-5)
Depth (ft bgs)
Antimony Concentration in mg/kg



FORMER EL PASO SMELTER SITE EL PASO, TEXAS
ANTIMONY DISTRIBUTION IN SOIL ACID PLANT ARROYO
FIGURE 4-44