


- LEGEND:
- DETECTED  $\leq$  SCREENING LEVEL
  - DETECTED  $>$  SCREENING LEVEL
  - HISTORICAL ARROYO TRACE LINES
  - - - PROPERTY BOUNDARY

NOTE:  
Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE EL PASO, TEXAS	
<b>SITE-WIDE DISTRIBUTION OF ARSENIC</b>	
	FIGURE <b>4-54</b>