


<b>Photo No.</b> <b>1</b>	<b>Date:</b> 07-12-16	
<b>Direction Photo Taken:</b>  View west		
<b>Description:</b>  View of area where slag was removed and sampled for confirmation.		

<b>Photo No.</b> <b>2</b>	<b>Date:</b> 07-28-16	
<b>Direction Photo Taken:</b>  View east		
<b>Description:</b>  View of former Pile 1 slag area. Demarcation fabric and backfill being placed on northern portion.		

<b>Photo No.</b> <b>3</b>	<b>Date:</b> 08-02-16	
<b>Direction Photo Taken:</b> View east		
<b>Description:</b> Two dozers grading slope while smooth drum roller compacts surface and 6k gal. waterwagon provides dust control.		

<b>Photo No.</b> <b>4</b>	<b>Date:</b> 08-08-16	
<b>Direction Photo Taken:</b> View east		
<b>Description:</b> Demarcation fabric and backfill being placed on southern portion.		

<b>Photo No.</b> <b>5</b>	<b>Date:</b> 12-08-16
<b>Direction Photo Taken:</b> View west	
<b>Description:</b> View of former Pile 1 slag area following completion of backfilling.	

