




CITY: Highlands Ranch DIV/GROUP: GIS DB: BG  
 Project (Project #):  
 Path: I:\ASARCO\_ElPaso\GIS\MXDIR\Revised\Fig 4-13 Lead Soil locations EastProp\_1.mxd Date: 9/13/2013 Time: 3:13:54 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
  - DETECTED > SCREENING LEVEL
  - HISTORICAL ARROYO TRACE LINES
  - - - PROPERTY BOUNDARY
  - AREA BOUNDARY

**NOTE:**  
 Screening Level (RRR SAI-Res = 500 mg/kg)  
**Bolded Value** exceeds screening level  
*Italics* Depth below groundwater  
 J = Estimated Value  
 U = Not detected at or above reporting limit  
 Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE  
EL PASO, TEXAS

**LEAD DISTRIBUTION IN SOIL  
EAST PROPERTY**

**MALCOLM  
PIRNIE**

**FIGURE  
4-13**