

CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #):
 Path: G:\GIS\ASARCO_ElPaso\GIS\MXDR\Revised\Response To Comments\Fig 4-24 Copper_SoilLocations_PBA2.mxd Date: 4/25/2014 Time: 11:01:48 AM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY
 - AREA BOUNDARY
 - FINES PILE BOUNDARY
 - BONEYARD BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 74000 mg/kg)



Bolded Value exceeds screening level

Italics indicate below the water table

J = Estimated Value

U = Not detected at or above reporting limit

Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
EL PASO, TEXAS

**COPPER DISTRIBUTION IN SOIL
PARKER BROTHERS ARROYO/BONEYARD**

**FIGURE
4-24**