


- LEGEND:
- DETECTED \leq SCREENING LEVEL
 - DETECTED $>$ SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY

NOTE:
Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE EL PASO, TEXAS	
SITE-WIDE SOIL DISTRIBUTION OF ARSENIC	
	FIGURE 4-57