

LEGEND:

- DETECTED ≤ SCREENING LEVEL
- DETECTED > SCREENING LEVEL
- HISTORICAL ARROYO TRACE LINES
- PROPERTY BOUNDARY
- AREA BOUNDARY

NOTE:
 Screening Level (RRR SAI-Res = 10000 mg/kg)



Bolded Value exceeds screening level

Italics indicate below the water table

J = Estimated Value

U = Not detected at or above reporting limit

Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
 EL PASO, TEXAS

**COPPER DISTRIBUTION IN SOIL
 EAST PROPERTY**

**MALCOLM
 PIRNIE**

**FIGURE
 4-12**