


CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #): El Paso GIS/MDIR/ Revised/Fig 4-18 Antimony Soil Locations PBA.mxd Date: 9/13/2013 Time: 3:16:26 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - PROPERTY BOUNDARY
 - AREA BOUNDARY
 - FINES PILE BOUNDARY
 - BONEYARD BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 490 mg/kg)



Bolded Value exceeds screening level

Italics indicate below the water table

J = Estimated Value

U = Not detected at or above reporting limit

Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
EL PASO, TEXAS

**ANTIMONY DISTRIBUTION IN SOIL
PARKER BROTHERS ARROYO/FINES PILE**

**MALCOLM
PIRNE**

**FIGURE
4-18**