



CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #): PBA2.mxd Date: 9/13/2013 Time: 3:19:33 PM
 Path: I:\ASARCO - El Paso\GIS\MXD\RI_ Revised\Fig 4-22 Cadmium_Soil Locations



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY
 - AREA BOUNDARY
 - FINES PILE BOUNDARY
 - BONEYARD BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 1500 mg/kg)
Bolded Value exceeds screening level
Italics indicate below the water table
 J = Estimated Value
 U = Not detected at or above reporting limit
 Date of Aerial Photo: 2009

Sample ID
 SL-07
 60.6 (0-0.5)
 Depth (ft bgs)
 Cadmium Concentration in mg/kg



FORMER EL PASO SMELTER SITE
 EL PASO, TEXAS

**CADMIUM DISTRIBUTION IN SOIL
 PARKER BROTHERS ARROYO/BONEYARD**

**MALCOLM
 PIRNIE**

**FIGURE
 4-22**