



LEGEND:

- DETECTED ≤ SCREENING LEVEL
- DETECTED > SCREENING LEVEL
- HISTORICAL ARROYO TRACE LINES
- PROPERTY BOUNDARY
- AREA BOUNDARY
- FINES PILE BOUNDARY
- BONEYARD BOUNDARY

NOTE:

Screening Level (RRR SAI-Ind = 74000 mg/kg)



Bolded Value exceeds screening level

Italics indicate below the water table

J = Estimated Value

U = Not detected at or above reporting limit

Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
 EL PASO, TEXAS

**COPPER DISTRIBUTION IN SOIL
 PARKER BROTHERS ARROYO/BONEYARD**



**FIGURE
 4-24**