




CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #): PBA2.mxd Date: 9/13/2013 Time: 3:22:06 PM
 Path: I:\ASARCO - El Paso\GIS\MXDR\I_ Revised\Fig 4-26 Lead Soil Locations



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY
 - AREA BOUNDARY
 - FINES PILE BOUNDARY
 - BONEYARD BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 1000 mg/kg)
Bolded Value exceeds screening level
Italics indicate below the water table
 J = Estimated Value
 U = Not detected at or above reporting limit
 Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
EL PASO, TEXAS

**LEAD DISTRIBUTION IN SOIL
PARKER BROTHERS ARROYO/BONEYARD**

**MALCOLM
PIRNIE**

**FIGURE
4-26**