


CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #):
 Path: I:\ASARCO - El Paso\GIS\MXDR\I_ Revised\Fig 4-29 Lead_Soil_locations_PlantEntrance.mxd Date: 9/13/2013 Time: 3:24:23 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY
 - AREA BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 1000 mg/kg)



Bolded Value exceeds screening level

Italics indicate below the water table

J = Estimated Value

U = Not detected at or above reporting limit

Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
EL PASO, TEXAS

**LEAD DISTRIBUTION IN SOIL
PLANT ENTRANCE**

**MALCOLM
PIRNIE**

**FIGURE
4-29**