




CITY: Highlands Ranch DIV/GROUP: GIS DB: BG
 Project (Project #): El Paso GISMXDIRI Revised Fig 4-48 Mercury Soil Locations AcidPlant.mxd Date: 9/13/2013 Time: 3:34:55 PM



- LEGEND:**
- DETECTED ≤ SCREENING LEVEL
 - DETECTED > SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY
 - AREA BOUNDARY

NOTE:
 Screening Level (RRR SAI-Ind = 0.15 mg/kg)
Bolded Value exceeds screening level
Italics indicate below the water table
 J = Estimated Value
 U = Not detected at or above reporting limit
 Date of Aerial Photo: 2009



FORMER EL PASO SMELTER SITE
EL PASO, TEXAS

**MERCURY DISTRIBUTION IN SOIL
ACID PLANT ARROYO**

**MALCOLM
PIRNIE**

**FIGURE
4-48**