


- LEGEND:
- DETECTED \leq SCREENING LEVEL
 - DETECTED $>$ SCREENING LEVEL
 - HISTORICAL ARROYO TRACE LINES
 - - - PROPERTY BOUNDARY

NOTE:
Date of Aerial Photo: 2009



| | |
|-----------------------------------------------|------------------------|
| FORMER EL PASO SMELTER SITE EL PASO, TEXAS | |
| SITE-WIDE DISTRIBUTION OF COPPER | |
| | FIGURE 4-57 |